



01272.020590

PATENT

## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

KENTARO YANO ET AL.

Appl. No.: 10/609,484

Filed: July 1, 2003

For: INK JET PRINTING APPARATUS,  
IMAGE PROCESSING METHOD AND  
CONTROL PROGRAM

U.S. Patent No.: 6,893,114 B2

Issued: May 17, 2005

Examiner: Thinh Nguyen

Group Art Unit: 2861

July 17, 2006

*Certificate  
of Correction  
JUL 20 2006*

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

**CERTIFICATE OF CORRECTION  
UNDER RULES 322 AND 323**

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

07/19/2006 MBEYENE1 00000033 6893114


01 FC:1811

100.00 OP

JUL 21 2006

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



Jeffrey M. Connor  
Attorney for Patentees  
Registration No.: 57,409

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
Facsimile: (212) 218-2200

JMC/gmc

DC\_MAIN 218235v1

Staple  
Here  
Only!

PRINTER'S TRIM LINE

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,893,114 B2

DATED : May 17, 2005

INVENTOR(S) : KENTARO YANO ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## COLUMN 5

Line 52, "ink" should read --inks--.

## COLUMN 6

Line 1, "ink" should read --inks--.

Line 16, "ink" should read --inks--.

Line 20, "process" should read --processes--.

## COLUMN 7

Line 35, "but" should read --and--, and "system" should read --systems--.

## COLUMN 9

Line 36, "microparticles" should read --microparticles to--.

Line 40, "drop-lets" should read --droplets--.

## COLUMN 10

Line 41, "moves" should read --move--.

## COLUMN 13

Line 30, "literatures" should read --literature--.

Line 59, "o(R," should read --  $\sigma$  (R,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. 6,893,114 B2

No. of add'l. copies  
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

JMC/gmc

→  
JUL 21 2006

Staple  
Here  
Only

PRINTER'S TRIM LINE

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,893,114 B2

DATED : May 17, 2005

INVENTOR(S) : KENTARO YANO ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## COLUMN 14

Line 42, "(e.g." should read --(e.g.,--.

Line 47, "P(e.g." should read --P(e.g.,--.

## COLUMN 17

Line 50, "his" should read --this--.

## COLUMN 19

Line 25, "smaller" should read --smaller than--.

## COLUMN 20

LINE 36, "process" should read --processes--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. 6,893,114 B2

No. of add'l. copies  
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

JMC/gmc

→ \_\_\_\_\_  
JUL 21 2006